


**ATTACHMENT 2:**

**Asbestos Containing Materials in Commuter Concourse**

## Building 100 - Terminal Building - Pier D - Section 4 - Lower



Please note that the asbestos-containing building materials (ACBM) identified on this drawing were identified during **NON-INTRUSIVE INSPECTIONS**. Additional suspect ACBM's may exist within wall cavities, chases, above fixed ceilings and other inaccessible areas. These materials should be assumed to be asbestos-containing unless future bulk sampling determines otherwise.

## Building 100 - Terminal Building - Pier D - Section 4 - Lower

Floor	Room Number	Room Description	HA Code	Homogeneous Area/Material	Quantity	Units
LD	DY 117	Vacant?	100-D14i-004	Sealant (general)	20	SF
LD	DY 122	Storage	100I-127	Mastic-floor	216	SF
LD	DY 122	Storage	100-1026	Fire Doors	2	EA
LD	DY 122D	Storage	100I-127	Mastic-floor	144	SF
LD	DY 126	Mechanical Room	100-1026	Fire Doors	1	EA
LD	DY 135(A)	Hall	100-1026	Fire Doors	1	EA
LD	DY 135B	Office	100-1026	Fire Doors	1	EA
LD	DY 137	Storage room	100-1026	Fire Doors	1	EA
LD	DY 140A	Wash area with closets and a hallway	100-1026	Fire Doors	5	EA
LD	DY 140B	Office area	100-1026	Fire Doors	1	EA
LD	DY 140C	Toilet	100-1026	Fire Doors	1	EA
LD	DY 140D	Toilet	100-1026	Fire Doors	1	EA
LD	DY 140E	Toilet	100-1026	Fire Doors	1	EA
LD	DY 148	Electrical Room	100-1026	Fire Doors	1	EA
LD	DY 149	Sewer Injection Room	100-1026	Fire Doors	2	EA
LD	DY 150	Mechanical Room	100-1026	Fire Doors	1	EA
LD	DY 155A	Storage Room	100-1026	Fire Doors	1	EA
LD	DY 157	Break room	100-1026	Fire Doors	1	EA
LD	DY 159	Maintenance supply	100-2057	Fire Doors	1	EA
LD	DY 163	Hall	100-1026	Fire Doors	1	EA
LD	DY 163A	Women's Room	100-1026	Fire Doors	1	EA

Please note that the asbestos-containing building materials (ACBM) identified on this drawing were identified during **NON-INTRUSIVE INSPECTIONS**. Additional suspect ACBM's may exist within wall cavities, chases, above fixed ceilings and other inaccessible areas. These materials should be assumed to be asbestos-containing unless future bulk sampling determines otherwise.

## Building 100 - Terminal Building - Pier D - Section 4 - Lower

Floor	Room Number	Room Description	HA Code	Homogeneous Area/Material	Quantity	Units
LD	DY 165A	Men's Room	100-1026	Fire Doors	1	EA
LD	DY 165B	Janitor's closet	100-2057	Fire Doors	1	EA

---

Please note that the asbestos-containing building materials (ACBM) identified on this drawing were identified during **NON-INTRUSIVE INSPECTIONS**. Additional suspect ACBM's may exist within wall cavities, chases, above fixed ceilings and other inaccessible areas. These materials should be assumed to be asbestos-containing unless future bulk sampling determines otherwise.